

# bosal

**Инструкция по монтажу  
тягово-цепного устройства  
шарового типа 3022 G  
для автомобилей  
Toyota  
Landcruiser 90**

	1996/10-2003
	2000
	100
	22.6



462800,

« - »

18



∴ (35363) 7-05-06  
/ : (35363) 7-13-20  
(495) 785-66-07

[www.bosal-autoflex.ru](http://www.bosal-autoflex.ru)


« - »:	
" (8182) 22-48-15	
" 8(8442) 98-74-98	
" 8(343) 379-39-89, 373-42-73	
" 8(343) 26-88-308	
" 8(3952) 710-194	
" 8(495) 777-54-59	
" 8(495)745-79-11	
" 8(495) 788-95-97	
" 8(495) 720-51-03	
" 8(3532) 57-99-85	
" 8-905-899-5012	
" 8(383) 291-59-60	
" 8(831) 279-53-24	
" 8(3422) 98-27-20	
" 8(342) 220-87-87	
" 8-927-002-90-06	
" 8(3462) 24-00-44	
" 8(3842) 21-14-76	
" 8-902-940-4151	
" 8(3452) 32-22-12, 41-52-62	
" 8-961-213-0278	
" 8-917-347-1700	
" 8(351) 269-44-75, 900-72-73	
" 8(3512) 773-76-91	

« »  
« »  
« »

1000



	1 .
	1 .
	1 .



	3 .
12 50	4 .
12 40	4 .
12 35	2 .
12 /	8 .
12	14 .
12	4 .
12	4 .
	2 .
( G)	1 .
	1 .
	1 .
190	1 .
	1 .